

Release Date	Models	OS	Version	Release Note
2023-09-05	PD2500Q/PD3205U PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U/PD2705U/ PD2506Q/PD2705UA/ PD3205UA/PD2706U PD2706UA	Windows 10/11	V2.4.2.0	Fix the issues below: a. The color mode shown on Display Pilot is not synchronized with the OSD menu when changing the color mode with the monitor's physical buttons b. When the ICCsync function is disabled, the ICC profile automatically changes to Display P3 every time the PC restarts
2023-02-14	PD2500Q/PD3205U PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U/PD2705U/ PD2506Q/PD2705UA/ PD3205UA/PD2706U PD2706UA	Windows 10/11	V2.3.74.0	Fix the issues below: a. Color mode = user, change Color Gamut value from Native to sRGB, Undo could be greyed out (PD2706U and PD2706UA) b. The input source is inconsistent with PD2706UA in the Display Page c. The color mode "Adobe RGB" should not be shown on the Color mode page for PD2706UA d. In HDR mode, the Saturation value in the software is inconsistent with the OSD (PD3205U and PD2725U)
2023-01-18	PD2500Q/PD3205U PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U/PD2705U/ PD2506Q/PD2705UA/ PD3205UA/PD2706U PD2706UA	Windows 10/11	V2.3.63.0	1. Support PD2706UA 2. Known issues: a. Color mode = user, change Color Gamut value from Native to sRGB, Undo could be greyed out (PD2706U and PD2706UA) b. The input source is inconsistent with PD2706UA in the Display Page c. The color mode "Adobe RGB" should not be shown on the Color mode page for PD2706UA d. In HDR mode, the Saturation value in the software is inconsistent with the OSD (PD3205U and PD2725U)
2022-12-27	PD2500Q/PD3205U PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U/PD2705U/ PD2506Q/PD2705UA/ PD3205UA/PD2706U	Windows 10/11	V2.3.52.0	1. Support PD2706U 2. Known issues: a. Not support PD2706UA yet b. Color mode = User, change Color Gamut value from Native to sRGB, Undo could be greyed out. c. Color mode = M-book, the User option shall be selected only in Color Temperature but it could be selected in the other options.
2022-10-13	PD2500Q/PD3205U PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U/PD2705U/ PD2506Q/PD2705UA/ PD3205UA	Windows 10/11	V2.3.15.0	1. Support PD2705UA/PD3205UA 2. Known issues: a. Color mode= HDR, Brightness text and Undo button will be partially covered by disabled blocks b. Color mode= HDR, the model name will disappear at the top right of the software window c. In the information page, the Input information is displayed as "USB-C I", not USB-C
2022-07-11	PD2500Q/PD3205U PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U/PD2705U/ PD2506Q	Windows 10/11	V2.2.95.0	1. Support PD2506Q 2. Known issues: a. When Color mode=ePaper, Sharpness value in Display Pilot won't sync to the value in OSD menu when users set Sharpness in OSD menu b. When clicks on the value field of Sharpness, the value of Sharpness increases. Suggest using the OSD menu to adjust Sharpness as a workaround. The two issues will be fixed in the next version.
2022-05-06	PD2500Q/PD3205U PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U/PD2705U/	Windows 10/11	V2.2.75.0	Fix issues 1. On the system page of Display Pilot, Win11 system shows Win10_64. 2. When opening PBP and the resolution changes to 1920x2160, it may occur a flickering issue.
2022-03-18	PD2500Q/PD3205U PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U/PD2705U/	Windows 10/11	V2.2.29.0	1. Add Support Models: PD2705U/PD3205U 2. Known Issue: When Opening PBP, the resolution is 1920x2160 which may occur flickering. The issue will be solved in the next version. The short-term solution is a. Turn off PBP b. or Change the resolution to 1920x1080 c. or Close Display Pilot.
2021-07-01	PD2500Q/PD2710QC/ PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U	Windows 7/8/10	V2.2.08.0	1. Solve the issue that the last color temperature setting values (6500K) of User mode cannot be restored when executing Undo.
2021-03-02	PD2500Q/PD2710QC/ PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U	Windows 7/8/10	V2.1.78.0	1. Solve the issue that display pilot does not work on Win7 systems 2. Solve the issue on AutoPivot function 3. Solve the issue that Hotkey setting does not be saved after restarting OS
2021-01-25	PD2500Q/PD2710QC/ PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q/ PD2725U	Windows 7/8/10	V2.1.65.0	1. Support New model PD2725U

2020-07-15	PD2500Q/PD2710QC/ PD2700Q/PD2700U/ PD3200Q/PD3200U/ PD2720U/PD3220U/ PD3420Q/PD2705Q	Windows 7/8/10	V2.1.19.0	1. Resolved bugs on Display Pilot
2020-06-04	PD2500Q/PD2710QC PD2700Q/PD2700U PD3200Q/PD3200U PD2720U/PD3220U PD3420Q/PD2705Q	Windows 7/8/10	V2.1.04.0	1. Add Korean language support
2020-05-04	PD2500Q/PD2710QC PD2700Q/PD2700U PD3200Q/PD3200U PD2720U/PD3220U PD3420Q/PD2705Q	Windows 7/8/10	V2.1.3.0	1. Compatible for all PD legacy models, & New MP models (PD3420Q/PD2705Q) 2. OTA(auto update) function. 3. B.I. button in Display Pilot.